








	Venue	Model year	Model displacement /fuel	mileage vehicle inspection	Evaluation exterior/interior	Start (1,000 yen)	
A メモ		<b>Toyota / Forklift</b> A 08009 car					
		2/8 (Thu) IMA Kyushu	2017	02-8FG25	0,000 km	/	0
						ナビ TV 取説	
						Other equipment:	
A メモ		<b>Mitsubishi / Forklift</b> A 08005 car					
		2/8 (Thu) IMA Kyushu	2018	FHGE25T5	0,000 km	/	0
						ナビ TV 取説	
						Other equipment:	
A メモ		<b>Toyota forklift /</b> D 62066 Car Vantra Small I Corner					
		2/6 (Tue) TAA Kyushu	2017	7FB15 /other	0,000 km	* /	300
						ナビ TV 取説	
						Other equipment:	
A メモ		<b>Toyota forklift /</b> C 62091 Car Vantra Small I Corner					
		2/6 (Tue) TAA Kyushu	2019	8FBE18 /other	0,000 km	* /	50
						ナビ TV 取説	
						Other equipment:	
A メモ		<b>Nissan forklift / shift fork</b> B 00024 Car ordinary car corner					
		2/8 (Thu) TAA Chubu	2011	UG1F2A30D	0,000 km	* /	50
						ナビ TV 取説	
						Other equipment:	
A メモ		<b>Komatsu forklift / side shift</b> A 00041 Car No. Ordinary car corner					
		2/8 (Thu) TAA Chubu	December 2020	FG15T-20	0,000 km	* /	50
						ナビ TV 取説	
						Other equipment:	
A B メモ		<b>Sumitomo Forklift /</b> B 00042 Car ordinary car corner					
		2/8 (Thu) TAA Chubu	2014	61FBR09NX2 /etc.	0,000 km	* /	Ten